

Division 3 Staff Meeting

March 2007

Safety & Health (Part 1)



Update:

- **Head Wall Fatality - OSH Closing Conference**
- **No Violation of the OSH Regulations**
- **Employer Knowledge**
- **Revision to SOP 11B-58 Pipe Installation**
- **Incorporated Crushing Hazard & Bracing Head Walls**

Dump Beds Attached To Trailers

Use a Spotter



Latch on window of 1999 Case Backhoe came open during transit, causing window to break.

Root Cause: Window not latched properly.

- The driver towing the equipment is responsible for securing the load before transport.
- PST – Primary, Secondary and Tertiary checks on all vehicles. It is a TEAM effort – operator and driver need to check load prior to transport.**

Excavator hit Tree Trunk,
Tree Limb hit power line,
Power grounded through Excavator





